

ਦਫ਼ਤਰ : ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਮਾਨਸਾ।

ਟੈਲੀਫੋਨ/ਫੈਕਸ ਨੰ: 01652-232119

Email ID :- xen.mansa@gmail.com

ਪੱਤਰ ਨੰ. 359

ਮਿਤੀ 13/05/2021

ਵੱਲ,

ਪ੍ਰਿੰਸੀਪਲ,

ਅਲਪਾਈਨ ਪਬਲਿਕ ਸੀ. ਸੈ. ਸਕੂਲ,

ਮਾਨਸਾ।

ਵਿਸ਼ਾ :- ਸਾਲ 2021-22 ਲਈ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕਰਨ ਸਬੰਧੀ।

ਹਵਾਲਾ:- ਆਪ ਦਾ ਪੱਤਰ ਨੰਬਰ 1421/AB/2021 ਮਿਤੀ 19/04/2021

ਤੁਹਾਡੇ ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਦਾ ਇੰਜੀਨੀਅਰ ਇੰਚਾਰਜ ਵੱਲੋਂ ਨਿਰੀਖਣ ਕੀਤਾ ਗਿਆ।
ਨਿਰੀਖਣ ਦੌਰਾਨ ਪਾਇਆ ਗਿਆ ਕਿ ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਸੇਫ ਹੈ। ਇਸ ਲਈ ਉਪ ਮੰਡਲ
ਇੰਜੀਨੀਅਰ ਵੱਲੋਂ ਕੀਤੀ ਸਿਫਾਰਸ਼ ਨੂੰ ਮੁੱਖ ਰੱਖਦੇ ਹੋਏ 31/03/2022 ਤੱਕ ਸਕੂਲ ਬਿਲਡਿੰਗ
ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ।

ਨੱਥੀ/ ਸਰਟੀਫਿਕੇਟ ਅਤੇ ਨਕਸ਼ਾ।



ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ,


ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਲੋ.ਨਿ.ਵਿ. ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਮਾਨਸਾ।

PERFORMA FOR THE SAFETY OF SCHOOL BUILDING

Part – 1

(To BE FILLED BY THE HEAD OF SCHOOL/INSTITUTE)

1. Name of the school : ALPINE PUBLIC SCHOOL (SEN.SEC.)MANSA
2. Location : N.M.COLLAGE ROAD MANSA
3. Plot Area : 48333.5/4
4. Plinth Area : 14321.125(N.F) + 14321.125 (W.F)
5. Number of storey's : 2
6. Year of Construction of the building : 2003-04
7. If the building has been constructed under the supervision of qualified Engineer,
Following details may be given: -
 - a) Name the engineer with qualification :BHARAT BHUSHAN BANSAL
 - b) Address of the engineer :DIPLOMA IN CIVIL ENG.
 - c) Attach structural drawings,
Used in the construction, if available :
 - d) Name the address of Architect with
Qualification :SHOP NO.25 GAUSHALA ROAD MANSA
8. Whether the building has been constructed for the purpose of
 - a) School : Yes
 - b) Residential purpose and
Converted as school : No
9. Materials used for roofs
 - a) RCCS Slabs : Yes
 - b) P.S. joists and battens : No
10. Materials used for walls
 - a) Mud Mortar : No
 - b) Cement Mortar : Yes
 - c) Plaster
 - a) Lime Mortar : No
 - b) Cement Mortar : Yes
11. a) Conglomerates : Yes
b) Terrazzo : No
12. A detail drawing indicating Dimensions
Of the rooms along with size and location
Of doors and windows


Principal
Alpine Public School, Mansa
CBSE Affi. No. 1630678
School No. 20560
Alpine Public School(Sen.Sec.)
Mansa


Building Safety Report


NAME OF SCHOOL:- ALPINE PUBLIC SCHOOL (SEN.SEC) MANSA
(District – MANSA)

As per report of...20.4.21..... Assistant/Junior Engineer on his visually inspection, the above mentioned school seems safe subject to the following observations and conditions.

1. The parameters to check the stability and safety of building such as structural Design, Architectural Drawings, Bearing capacity, Foundation details, Structural drawings, Technical Specification, Test reports of Material used and Quality control reports are not available.
2. In case any addition, alteration, expansion and modification to this building are required/to be done, regarding this, inspection to undersigned may be arranged and obtained a certification the completion from the undersigned.
3. In case of building is affected by flood or if there is any settlement of walls foundation of roof etc. immediately inspection of the undersigned arranged to check the stability and safety of the building.
4. A separate certificate regarding Fire Fighting should be obtained from the competent Authority.
5. A separate certificate regarding Electrical works should be obtained from the competent Authority.
6. The owner of the building/Management is fully responsible regarding safety of the building from all angles in spite of this report.
7. This report for the covered area of the school building 28642.00...sqft which is submitted by the owner of the school building as per drawing.
8. The building of the school is constructed as framed structure/brick masonry.
9. This report is not valid for legal purpose.
10. That the fee charges for the year ...2021-22....

As per visually inspection as reported by the concerned Assistant/ Junior Engineer the above building may be used for normal use for One year up to 26-8-21..... Subject to the above conditions


Assistant/ Junior Engineer


Sub Divisional Engineer
Provl. Sub Divin. P.W.D. B&R No.:-1
MANSA